








































	GR6 HBA318	No	7	7	7	7	-	SPST-NO	A	0.4	5*	0.050	2	1	100	20@ 10- 500	100 million	24
	FRD 12000		10	10	6	6												
	GR6 JNB218	No	8	8	8	8	-	SPST-NC	B	4	3*	0.050	3	2	100	20@ 10- 500	100 million	5
	FRD 12021		8	8	6	6												
	GH2	No	8	-	-	-	500	SPDT	C	-	-	0.010	6	6	50	10@ 55- 2000	2 million	40
	x		25	-	-	-												
	GH4	Yes	8	-	-	-	500	SPDT	C	-	-	0.020	6	6	50	10@ 55- 2000	2 million	40
	x		15	-	-	-												
	GH6	Make Only	8	-	-	-	500	SPDT	C	-	-	0.500	6	6	50	10@ 55- 2000	1 million	40
	x		8	-	-	-												
	G12	Yes	8	5	3	2	500	DPDT	2C	0.8	1.5	0.020	15	9	30	10@ 10- 2000	1 million	71
	x		10	7	3	2												
	G12L	Yes	8	5	3	2	500	LATCHING DPDT	2C	0.8	1.5	0.020	15	9	30	10@ 10- 2000	1 million	71
	x		10	7	3	2												
	G47A	Yes	8	7.5	7	5	500	SPST-NO	A	1.2	1.2	0.030	10	10	30	10@ 55- 1000	2 million	26
	x		12	10	5	3												
	G47B	Yes	8	7.5	7	5	500	SPST-NC	B	1.2	1.2	0.030	10	10	30	10@ 55- 1000	2 million	26
	x		12	10	5	3												
	G43A	Yes	10	7	6	4	500	SPST-NO	A	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	x		25	20	13	10												
	G43B	Yes	10	7	6	4	500	SPST-NC	B	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	x		25	20	13	10												
	G43C	Yes	10	7	6	4	500	SPDT	C	1.2	1.2	0.020	10	10	50	10@ 55- 2000	2 million	28
	x		25	20	13	10												
	G81A G81B	Yes	10	-	-	-	-	SPST-NO SPDT-NC	A B	-	-	0.030	10	10	30	10@ 55- 500	2 million	57
	x		5, 20 or 30	-	-	-												
	G81C	Yes	10	-	-	-	-	SPDT	C	-	-	0.050	10	10	30	10@ 55- 500	2 million	71
	x		5 or 30	-	-	-												

	GR5LTA	Yes	10	-	-	-	-	SPST-NO	A	1	8*	0.250	2	2	100	20@ 10- 500	1 billion	28
	DAT7**10		5	-	-	-												
	GR5LTB	Yes	10	-	-	-	-	SPST-NC	B	1	8*	0.250	2	2	100	20@ 10- 500	1 billion	28
	DBT7**10		5	-	-	-												
	G2	No	15	12	9	7	500	SPDT	C	0.5	1	0.012	15	9	50	10@ 55- 500	1 million	85
	x		50	30	17	10												
	G2L	No	15	12	9	7	500	LATCHING SPDT	C	0.5	1	0.012	15	9	50	10@ 55- 500	1 million	85
	x		50	30	17	10												
	G8	Yes	15	-	-	-	500	SPDT	C	0.5	1	0.025	15	9	50	10@ 55- 500	1 million	85
	x		30	-	-	-												
	G8L	Yes	15	-	-	-	500	LATCHING SPDT	C	0.5	1	0.025	15	9	50	10@ 55- 500	1 million	85
	x		30	-	-	-												
	G9	Yes	15	13	10	-	500	SPDT	C	3	3.5	0.010	30	8	50	10@ 55- 500	1 million	300
	x		75	35	22	-												
	G15	Make Only	15	-	-	-	500	SPDT	C	-	-	1.0	15	9	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G15L	Make Only	15	-	-	-	500	LATCHING SPDT	C	-	-	1.0	15	9	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G13	Make Only	15	-	-	-	500	DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	142
	x		10	-	-	-												
	G13L	Make Only	15	-	-	-	500	LATCHING DPDT	2C	0.5	1	1.0	15	9	50	10@ 55- 500	1 million	142
	x		10	-	-	-												
	G23	No	15	13	10	-	500	DPDT	2C	3	3.5	0.010	30	10	50	10@ 55- 300	1 million	380
	x		75	35	22	-												
	GR5MTA	Yes	15	-	-	-	-	SPST-NO	A	1	8*	0.250	3	2	100	20@ 10- 500	100 million	28
	DAT7**15		5	-	-	-												
	G22	Yes	25	-	-	-	500	SPST-NO	X	2.5	2.5	0.005	18	10	30	10@ 55- 500	2 million	342
	x		65	-	-	-												
	G62	Yes	25	-	-	-	500	SPST-NO SPDT-NC SPDT	A B C	-	-	0.500	15	15	20	10@ 55- 500	1 million	340
	x		18	-	-	-												
	G62L	Yes	25	-	-	-	500	LATCHING SPST	A	-	-	0.500	15	15	20	10@ 55-	1 million	340

	x		18	-	-			SPDT	C							500		
	G50	Yes	25	-	-	-	500	SPDT	C	5	5	0.005	100	15	30	10@ 55- 500	1 million	992
	x		110	-	-	-												
	G52	Yes limited	25	15	10	7	500	SPDT	C	5	5	0.003	100	15	30	10@ 55- 500	1 million	992
	x		150	120	75	30												
	G20	No	28	22	12	10	500	SPST-NO	X	2.5	2.5	0.005	18	10	30	10@ 55- 500	2 million	342
	x		110	60	40	30												
	G60C	Make Only	35	-	-	-	500	SPDT	C	-	-	1.0	15	15	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G60L	Make Only	35	-	-	-	500	LATCHING SPDT	C	-	-	1.0	15	15	50	10@ 55- 500	1 million	85
	x		12	-	-	-												
	G61	Make Only	35	-	-	-	500	SPST-NO SPDT-NC SPDT	A B C	-	-	1.0	15	15	20	10@ 55- 500	1 million	336
	x		10	-	-	-												
	G61L	Make Only	35	-	-	-	500	LATCHING SPST SPDT	A C	-	-	1.0	15	15	20	10@ 55- 500	1 million	336
	x		10	-	-	-												
	G64C	Make Only	50	-	-	-	500	SPDT	C	-	-	1.0	15	15	10	10@ 55- 500	1 million	340
	x		10	-	-	-												
	G64L	Make Only	50	-	-	-	500	LATCHING SPDT	C	-	-	1.0	15	15	10	10@ 55- 500	1 million	340
	x		10	-	-	-												
	G71	Make Only	70 ***	-	-	-	500	SPST-NO SPDT-NC SPDT	A B C	-	-	2.0	20	15	20	10@ 55- 500	.5 million	336
	x		10	-	-	-												
	G71L	Make Only	70 ***	-	-	-	500	LATCHING SPST SPDT	A C	-	-	2.0	20	15	20	10@ 55- 500	.5 million	336
	x		10	-	-	-												

*Closed contacts to ground.

***30 kV at 60Hz

12/19/05